Partial fill insulation to gable walls

(Withdrawn - January 2024)

The Technical Guidance Notes are produced by NHBC as guidance solely for our builder customers as to how to interpret the technical requirements in relation to the warranty cover provided by NHBC under its Buildmark, Buildmark Choice, Buildmark Link, Buildmark Solo, Buildmark Connect or any similar product from time to time. It has not been created or intended for distribution or use outside of that purpose. The information contained in this Technical Guidance Note does not constitute advice and is not to be relied upon by any third party. Nothing in this Technical Guidance Note is intended to, nor should it be taken to, create any legal or contractual relationship. Any third party who chooses to rely upon the information contained in the Technical Guidance Notes shall do so entirely at their own risk and NHBC accepts no duty of care or liability, however caused, in connection with its use or reliance by any third party.

Question

Where partial fill insulation is placed in the cavity but does not continue to the top of the gable wall is a cavity tray needed?

Considerations

Mortar droppings may collect on the top edge of the insulation and bridge the cavity.

Answer

Installing a cavity tray with weepholes above is good practice and should not be discouraged. However, provided workmanship is acceptable and insulation is adequately retained against the inner leaf, so that there is a nominal 50mm clear cavity between the insulation and the outer leaf, a cavity tray is not needed.



NHBC, NHBC House, Davy Avenue, Knowlhill, Milton Keynes, Bucks MK5 8FP Tel: 0344 633 1000 Web: nhbc.co.uk