

Guarding to retaining structures in communal areas

(November 2024) (Third issue – supersedes June 2022)

The Technical Guidance Notes are produced by NHBC as guidance solely for our builder customers as to how to interpret the technical requirements in relation to the warranty cover provided by NHBC under its Buildmark, Buildmark Choice, Buildmark Link, Buildmark Solo, Buildmark Connect or any similar product from time to time. It has not been created or intended for distribution or use outside of that purpose. The information contained in this Technical Guidance Note does not constitute advice and is not to be relied upon by any third party. Nothing in this Technical Guidance Note is intended to, nor should it be taken to, create any legal or contractual relationship. Any third party who chooses to rely upon the information contained in the Technical Guidance Notes shall do so entirely at their own risk and NHBC accepts no duty of care or liability, however caused, in connection with its use or reliance by any third party.

Question

Should guarding provided to retaining walls in communal areas be not readily climbable by children?

Considerations

- NHBC Standards 'Guarding and steps', clause 10.2.5 states guarding should be provided where structures are retaining land more than 600mm high to which people have access.
- NHBC Standards clause 10.2.5 goes on to say that the guarding should be at least 1100mm high, not readily climbable by children and a 100mm sphere should not be able to pass through any openings in the guarding.
- Technical Guidance 10.2/06 describes guarding requirements where the ground at the foot of a retaining structure slopes away.

Answer

In communal areas where structures retain land more than 600mm high to which people have access the difference in ground level should be guarded to prevent falling.

The reference to 'Garden areas' under NHBC Standards clause 10.2.5 applies to both private and communal areas. The guarding should therefore be at least 1100mm high, not readily climbable by children and a 100mm sphere should not be able to pass through any openings in the guarding.

Reference should be made to Technical Guidance 10.2/06 for guarding requirements where the ground at the foot of a retaining structure slopes away.



NHBC, NHBC House, Davy Avenue, Knowlhill, Milton Keynes, Bucks MK5 8FP
Tel: 0344 633 1000 Web: nhbc.co.uk

National House-Building Council (NHBC) is authorised by the Prudential Regulation Authority and regulated by the Financial Conduct Authority and the Prudential Regulation Authority for carrying on insurance business and insurance distribution activities.

NHBC is registered in England and Wales under company number 00320784. NHBC's registered address is NHBC House, Davy Avenue, Knowlhill, Milton Keynes, Buckinghamshire, MK5 8FP. Note that only certain parts of our products and services are within the scope of UK financial services regulations. For more information on our products and services, please see our website [nhbc.co.uk](https://www.nhbc.co.uk) or your NHBC product documentation.