

# DPC trays to rendered walls

(Withdrawn – January 2024)

The Technical Guidance Notes are produced by NHBC as guidance solely for our builder customers as to how to interpret the technical requirements in relation to the warranty cover provided by NHBC under its Buildmark, Buildmark Choice, Buildmark Link, Buildmark Solo, Buildmark Connect or any similar product from time to time. It has not been created or intended for distribution or use outside of that purpose. The information contained in this Technical Guidance Note does not constitute advice and is not to be relied upon by any third party. Nothing in this Technical Guidance Note is intended to, nor should it be taken to, create any legal or contractual relationship. Any third party who chooses to rely upon the information contained in the Technical Guidance Notes shall do so entirely at their own risk and NHBC accepts no duty of care or liability, however caused, in connection with its use or reliance by any third party.

## Question

On fully rendered masonry walls do cavity trays need to be provided over openings and roof abutments? If so do they require weepholes and stop ends?

## Considerations

- Wind-driven rain may penetrate rendered masonry through minor cracks and around openings, architectural details etc.
- NHBC Standards Chapter 6.11 'Render' provides guidance on the provision of weepholes in rendered walls.

## Answer

### Openings

Cavity trays with stop ends are required over all openings.

Weepholes are required where render is returned back onto the window/door frame at the head of an opening. Weepholes are not required where the render is not returned or only returns to the toe of the lintel, leaving the underside of the lintel exposed.

Where required a minimum of two weepholes per opening should be provided.

### Roof abutments

Cavity trays are required at all roof abutments.

Preformed stepped cavity trays should be provided at raking abutments with a weephole at the bottom tray.

A site made or preformed cavity tray should be provided at horizontal abutments with weepholes at maximum 1m centres.



**NHBC, NHBC House, Davy Avenue, Knowlhill, Milton Keynes, Bucks MK5 8FP**  
**Tel: 0344 633 1000 Web: nhbc.co.uk**

National House-Building Council (NHBC) is authorised by the Prudential Regulation Authority and regulated by the Financial Conduct Authority and the Prudential Regulation Authority for carrying on insurance business and insurance distribution activities.

NHBC is registered in England and Wales under company number 00320784. NHBC's registered address is NHBC House, Davy Avenue, Knowlhill, Milton Keynes, Buckinghamshire, MK5 8FP. Note that only certain parts of our products and services are within the scope of UK financial services regulations. For more information on our products and services, please see our website nhbc.co.uk or your NHBC product documentation.