Japanese Knotweed

(August 2024) (Fourth issue - supersedes December 2016)

The Technical Guidance Notes are produced by NHBC as guidance solely for our builder customers as to how to interpret the technical requirements in relation to the warranty cover provided by NHBC under its Buildmark, Buildmark Choice, Buildmark Link, Buildmark Solo, Buildmark Connect or any similar product from time to time. It has not been created or intended for distribution or use outside of that purpose. The information contained in this Technical Guidance Note does not constitute advice and is not to be relied upon by any third party. Nothing in this Technical Guidance Note is intended to, nor should it be taken to, create any legal or contractual relationship. Any third party who chooses to rely upon the information contained in the Technical Guidance Notes shall do so entirely at their own risk and NHBC accepts no duty of care or liability, however caused, in connection with its use or reliance by any third party.

Question

Where Japanese Knotweed is found on a site what action should be taken?

Considerations

- Although Japanese Knotweed has a vigorous growth and can be difficult to eradicate, it has not been found to cause structural damage.
- It can grow through, and cause damage to, paved and tarmaced surfaces.
- There is strict legislation regarding its management and disposal.

Answer

Where Japanese Knotweed is found on a site advice on its control and disposal can be found at websites of the following organisations that operate Codes of Practice and/or Technical Standards for dealing with invasive species:-

Environment Agency at www.gov.uk/government/organisations/environment-agency

INNSA - Invasive Non-Native Specialists Association at www.innsa.org/information

PCA - Property Care Association at www.property-care.org/homeowners/invasive-weed-control/



NHBC, NHBC House, Davy Avenue, Knowlhill, Milton Keynes, Bucks MK5 8FP Tel: 0344 633 1000 Web: nhbc.co.uk