## Access to manholes/inspection chambers

(August 2024) (Second issue - supersedes December 2008)

The Technical Guidance Notes are produced by NHBC as guidance solely for our builder customers as to how to interpret the technical requirements in relation to the warranty cover provided by NHBC under its Buildmark, Buildmark Choice, Buildmark Link, Buildmark Solo, Buildmark Connect or any similar product from time to time. It has not been created or intended for distribution or use outside of that purpose. The information contained in this Technical Guidance Note does not constitute advice and is not to be relied upon by any third party. Nothing in this Technical Guidance Note is intended to, nor should it be taken to, create any legal or contractual relationship. Any third party who chooses to rely upon the information contained in the Technical Guidance Notes shall do so entirely at their own risk and NHBC accepts no duty of care or liability, however caused, in connection with its use or reliance by any third party.

## **Question**

If a manhole/inspection chamber is sited under a fence what action should be taken to ensure reasonable access is provided?

## **Considerations**

- Manholes/inspection chambers should be readily accessible for inspection and maintenance.
- Covers to drainage systems should not be obstructed by boundary fences.

## **Answer**

Manholes/inspection chambers should be located to provide adequate access for inspection and maintenance.

Where a manhole/inspection chamber is obstructed by a fence, either the fence or the manhole/inspection chamber should be relocated.

In exceptional circumstances a removable fence panel can be accepted provided that the fence panel can be removed easily (e.g. by the removal of a few bolts).



NHBC, NHBC House, Davy Avenue, Knowlhill, Milton Keynes, Bucks MK5 8FP Tel: 0344 633 1000 Web: nhbc.co.uk