## Handrail to staircases tapered treads/winders

(Withdrawn - January 2024)

The Technical Guidance Notes are produced by NHBC as guidance solely for our builder customers as to how to interpret the technical requirements in relation to the warranty cover provided by NHBC under its Buildmark, Buildmark Choice, Buildmark Link, Buildmark Solo, Buildmark Connect or any similar product from time to time. It has not been created or intended for distribution or use outside of that purpose. The information contained in this Technical Guidance Note does not constitute advice and is not to be relied upon by any third party. Nothing in this Technical Guidance Note is intended to, nor should it be taken to, create any legal or contractual relationship. Any third party who chooses to rely upon the information contained in the Technical Guidance Notes shall do so entirely at their own risk and NHBC accepts no duty of care or liability, however caused, in connection with its use or reliance by any third party.

### Question

Where stairs have tapered treads/winders, is a handrail required to the outside of the stairs?


#### **Considerations**

- A safe handhold is required for the full rise of any stairs with a total rise greater than 600mm.
- A suitable newel post can provide a safe handhold.

### **Answer**

### Single newel

In England, Wales and Scotland where the stairs have between one and four tapered treads/winders and the newel provides a safe handhold, a handrail is not required to the outside of the stairs.



#### **Double newels**

In England, Wales and Scotland where the newels provide a safe handhold, a handrail is not required to the outside of the stairs.



<sup>\*</sup> In Northern Ireland a handrail should be tted to the outside of all tapered stairs (required by building regulations).



# Handrail to staircases tapered treads/winders

(Withdrawn - January 2024)

Where a handrail is needed to the outside of the stairs, it should be continuous for the whole rise to avoid the need to change hands. Handrails need not join at corners to be considered continuous provided they extends into the corner and provide an easy transfer of a handhold from one handrail to the other.




Figure 1



NHBC, NHBC House, Davy Avenue, Knowlhill, Milton Keynes, Bucks MK5 8FP Tel: 0344 633 1000 Web: nhbc.co.uk

National House-Building Council (NHBC) is authorised by the Prudential Regulation Authority and regulated by the Financial Conduct Authority and the Prudential Regulation Authority for carrying on insurance business and insurance distribution activities.