

Movement joints below DPC

(February 2024) (Second issue – supersedes March 2021)

The Technical Guidance Notes are produced by NHBC as guidance solely for our builder customers as to how to interpret the technical requirements in relation to the warranty cover provided by NHBC under its Buildmark, Buildmark Choice, Buildmark Link, Buildmark Solo, Buildmark Connect or any similar product from time to time. It has not been created or intended for distribution or use outside of that purpose. The information contained in this Technical Guidance Note does not constitute advice and is not to be relied upon by any third party. Nothing in this Technical Guidance Note is intended to, nor should it be taken to, create any legal or contractual relationship. Any third party who chooses to rely upon the information contained in the Technical Guidance Notes shall do so entirely at their own risk and NHBC accepts no duty of care or liability, however caused, in connection with its use or reliance by any third party.

Question

Should movement joints in external walls extend below the DPC?

Considerations

- NHBC Standards Clause 6.1.3 says “Any movement joints should continue from those provided in the substructure to the superstructure. Movement joints may be needed in the superstructure where none are required in the substructure – however suitable allowance should be made for relative movement”.
- Movement in masonry can be caused by a number of factors including changes in temperature, changes in moisture content and differential ground movement.
- The orientation of a wall in relation to the sun will have an effect on the degree of thermal movement that will take place.
- PD 6697 *Recommendations for the design of masonry structures to BS EN 1996-1-1 and BS EN 1996-2* gives guidance on the provision of movement joints.

Answer

It is the designer’s responsibility to ensure movement joints are designed to suit the actual layout and design of the structure. The following should be taken into consideration:

1. Where the DPC is less than 600mm above ground level, movement joints for expansion do not generally need to extend below the DPC.
2. Where the DPC is more than 600mm above ground level, consideration should be given to continuing the expansion joint through the masonry below the DPC.
3. Where the movement joint is provided for vertical differential ground movement, for example:
 - a. at major changes in foundation levels, or
 - b. between foundations of different designs, or
 - c. at variations in the height of the building, the movement joint should continue through the masonry below the DPC.



NHBC, NHBC House, Davy Avenue, Knowlhill, Milton Keynes, Bucks MK5 8FP
Tel: 0344 633 1000 Web: nhbc.co.uk

National House-Building Council (NHBC) is authorised by the Prudential Regulation Authority and regulated by the Financial Conduct Authority and the Prudential Regulation Authority for carrying on insurance business and insurance distribution activities.

NHBC is registered in England and Wales under company number 00320784. NHBC's registered address is NHBC House, Davy Avenue, Knowlhill, Milton Keynes, Buckinghamshire, MK5 8FP. Note that only certain parts of our products and services are within the scope of UK financial services regulations. For more information on our products and services, please see our website nhbc.co.uk or your NHBC product documentation.